

FIG. 1




Fig. 1




Fig. 2




FIG. 3A




FIG. 3B

FIG. 4




FIG. 4






Fig. 5

FO5007 DTET0660



6A


SEM Micrograph of Group B at 300x after Electrochemical Test.




6B

SEM Micrograph of Group B at 700x after electrochemical test.

09501310-100501



7A




7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.

70500T 07E70660



7C



7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.



